



The iP-CB can be reset to factory settings without using the CVs by using the following process:

- 1 Turn **OFF** power to the iP-CB.
- 2 Hold the **RESET** button down **WHILE** restoring power to the iP-CB.
- 3 Release the RESET button the SET/RUN LED will flash steadily.
- 4 Within 5 seconds press the **RESET** button again.
- 5 The iP-CB will return to normal operation with the main LED on the aluminium constantly lit.